

OAKHURST SAFETY INSPECTION REPORT

OAKHURST	Issue	Surface	Date									
Equipment & Surface			15.03.22									
Mushrooms x 3	Needs painting	N/A										
Rocker Horse <table border="1" style="width: 100%; height: 30px;"> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> </table>										Needs painting	No issues	
Spinner	No issue	Safety surface is 'splitting' where repaired due to weeds. This would benefit from attention before it gets any worse.										
2 Bay 4 Cradle Seat Swing Surface	None	Wear under children's swing.										
Toddler & Multi Play	Broken chain link on 'climbing' element	No issue										
Ancillary												
Bench x 2	Untidy, need painting	No issues										
Boundary												
Fence Chain Link	None											
Fence – post and rail/wire mesh	None											

OAKHUST SAFETY INSPECTION REPORT

Pedestrian Gate Play Area	Sticking		
FIELD			
Goal Post – field	Satisfactory		
Overhead Rotator - field	No issue	No issue	
Maintenance Gate – Field (Wooden)	None		
Pedestrian Gate - Field	Doesn't shut properly.		
Pedestrian Gate - Field (Wooden)	Extreme movement in post.		
Pedestrian Gate - Play Area to Field	No issue		

Signature M.L.Jordan.....

Date and time2.00pm 15.03.22.....