

## PLAY PARK EQUIPMENT SAFETY INSPECTION SHEET

<b>LOCATION</b>	<b>DATE 15 July 2022</b>
<b>CHAPEL HAY</b>	<b>TIME 4.00pm</b>
<b>Equipment &amp; Surface</b>	<b>COMMENTS</b>
<b>Roundabout</b>	Satisfactory - but rather grubby. Surface uneven
<b>2 Bay x4 Junior Swings</b>	<b>Seats beginning to crack. Low risk</b> <b>Surface: holes appearing. Breaking up in places</b>
<b>1 Bay X 2 Cradle Seat Swings</b>	OK
<b>Slit Slide</b>	OK
<b>Igloo Climber</b>	OK
<b>See Saw</b>	OK
<b>Pedestrian Gate / Fence/Gate to Station Road/Boundary</b>	No latch. Fence ok, but one or two places unsatisfactory. Boundaries generally satisfactory
<b>Goal Posts</b>	Sound
<b>Notice Board</b>	Good
<b>Benches</b>	Generally satisfactory or good
<b>Signage</b>	Adequate
<b>Refuse/ Dog Bins</b>	OK

## PLAY PARK EQUIPMENT SAFETY INSPECTION SHEET

**NAME:** Cllr Ian YATES

**SIGNATURE** Ian Yates